

MEMORIAL POOL SLAB ON GRADE OBSERVATIONS - 9-12-2024



Slab on grade crack runs the length of the lap pool on the south side.



Slab on grade crack runs the length of the lap pool on the north side.



Slab on grade subsidized on the west side of the leisure pool. Top of concrete was ground flush to avoid tripping hazards.



Slab on grade subsidized on the east side of the leisure pool. Top of concrete was ground flush to avoid tripping hazards.